



MODEL **444**

CARBURETTOR

Carburettor compl. type HDC 51 B, reference number 501 45 67-05 is excluded and replaced by carburettor compl. to the model 44, type HDA 24, reference number 50 17 980-01.

When exchanging the carburettor the following parts also need to be replaced (see below).

Test run and check:

- That you by idling speed do not receive any rpm-increase when you load the bar.  
Hold the saw idling against a log and apply force on the handles, as if you should cut.
- That full throttle is received when you apply full throttle on the trigger.

Inform your client that the throttle latch function also is moved to the choke (see model 44).

The throttle latch on the rear handle can be removed.

