





SERVICE 		1
		X 86.109-26

MODELS **238, 44**

OIL TANK VENTILATION

The repair kit consists of a split pin and a roll pin and they are assembled instead of the sinter plug. See below.

This gives a more secure tank ventilation.

