





SERVICE 		10
		X 91.140-26

MODEL 165 RX

DRIVE SHAFT

In order to further strengthen the joint between the drive shaft and the clutch drum a new stop sleeve has been added to the drive shaft.

The new stop sleeve is pressed on the drive shaft with a tight fit and therefore counteract any movement in the joint.

The Ref. no. for the complete drive shaft, remains the same: 502 25 78-01.

The new drive shaft can be recognized by the bevel on the stop sleeve.

Introduced from serial no. 1090001.

