





SERVICE 		10 X 94.157-26
--	--	--------------------------

Model 225/232

Gear housing

The clamping joint on the gear housing has been fitted with two screws instead of one. The clamping force is now distributed more evenly along the shaft. At the same time the edge of the gear housing that joins the shaft has been bevelled.

Introduced into production from week 38.

