



Model

Rider 850 and Rider 970, 1995 models

Keyway in the rear rim

The keyway in the rim has in some cases been too high. This results in insufficient key grip on the rear axle causing the rim to revolve on the axle. There is a higher key (6.0 mm) available as a service part, ref no. 506 94 50-01. Machines with serial numbers from 440 0001 to 532 9999 can have this problem and we recommend changing to the new key. If the rim is damaged this should also be changed.

New Ref. No.	Description	Excl. Ref. No.	Remark
506 94 50-01	Keyway	-	

