

Model 235P

Top extension

A plastic top extension (ball joint) has been introduced on the pruner. The components have a lower weight and cost less.

The old aluminium components have been discontinued and cannot be replaced individually by the new plastic components.

New Ref. No.	Description	Excl. Ref. No.	Remark
503 82 97-10	Ball joint complete	-	
502 42 59-01	Lock nut	-	
502 42 58-01	Joint ball	503 73 32-02	
502 42 57-01	Joint socket	502 40 48-01	
503 21 06-25	Bolt 5.5x25	-	

compl 503 82 97-10

