





SERVICE 		4
		B9900004

English 1 (1)

SB, 335 XPT, Tank, 1999-02

A new tank has been brought into production with the following improvements:

- In response to requests from customers the size of the thumb and forefinger supports has been reduced.
- The appearance of the tank has been changed to eliminate the risk of the oil pump nipple on the crankcase fouling the tank wall.
- The tank vent pipe that is built into the tank has been extended to improve tank venting.

All these improvements were introduced **from production code N.**

New ref. no.	Description	Excl. ref. no.	Remarks
503 79 21-72	Tank assy.	503 79 21-71	R

Introduced from serial number: 8500001

