

SB, 335 XPT, Flywheel, 1999-02

The flywheel has been modified to reduce the risk of the starter pawls slipping on the pulley during starting.

The fan blades, which act as a speed limiter for the pawls, have been adjusted so that the pawls remain nearer the centre in the rest position.

Until the corresponding modifications are made to production moulds the current flywheel will be re-machined to produce the new version. These can easily be identified by the blue marking and the fact that two of the blades have been machined. See fig. A.

The new version will have production code H.

New ref. no.	Description	Excl. ref. no.	Remarks
503 79 06-03	Flywheel assy.	503 79 06-02	

Introduced from serial number: 8500001

