





<b>SERVICE</b> 		<b>3</b>
		<b>B9901027</b>


English 1 (1)

## SB, 55 Rancher, 55, 51, Ignition module, 1999-09

A new ignition module has been introduced on the above models. The new ignition module is fully interchangeable with the earlier variant.

New ref. no.	Description	Excl. ref. no.	Remarks
503 90 14-01	Ignition module	503 90 12-01	

Introduced into production from serial number:	55 Rancher	91102001
	55	91300901
	51	91200701



503 90 14-01