


For Husqvarna Parts Call 606-678-9623 or 606-561-4983



## Product Service Bulletin



030399-02

1999-02

Engineering Services

**Models Affected:** LTH 130, YTH 145, YTH 150, YTH 180, GTVH 200

**Serial Numbers:** 100198xxxxxx through 123198xxxxxx

**Issue Reported:** These affected models and serial numbers were inadvertently shipped without axle support brackets installed in production. These brackets assist in positioning the front axle for a proper fit in the axle saddle. Units after this serial number have the axle brackets installed in production.

**Action Required:** Axle bracket kits have been shipped at no charge to each dealer in the quantity required, based on our shipping information, for installation on the affected units. Install the axle bracket kits following the instructions enclosed with each set of brackets. Contact the Engineering Support Group if you did not receive kits for any units listed in this serial range by March 31, 1999.

