

SAFETY RECALL


MTD, MTD GOLD, CUB CADET, TROY-BILT, CRAFTSMAN 21, 25, 27 and 33 TON LOGSPLITTERS

The Splitting Wedge may continue to move forward after the operator releases the Control Handle from the Forward position **posing a risk of serious injury to the operator's hand and fingers.**

Do not use the logsplitter until you have contacted Customer Service.

Models Affected

Brand Name	Model Number
MTD Gold	24BF510B004
MTD Gold	24BF510E204
MTD Gold	24BF570L004
MTD Gold	24BF570F204
Troy-Bilt	24BF572B766
Troy-Bilt	24AD597D766
Troy-Bilt	24BF572B711
Troy-Bilt	24AD597D711
Yard Machines	24BF552B729
Yard Machines	24BF550B029
Cub Cadet	24BF572B756
Cub Cadet	24BF572B710
Cub Cadet	24AD598A010
MTD	24BF550M006
Craftsman	247.7764
Craftsman	247.77641



Sold between November 2008 and October 2009.


**To receive free inspection instructions and repair, if needed, call
Customer Service toll-free between
8:00 AM and 5:00 PM EST Monday through Friday or
Saturday 10:00 AM to 3:00 PM EST**

**Call 1-888-848-6038
or speak with your authorized service dealer**

In cooperation with the U.S. Consumer Product Safety Commission


24AD597D766 LS33 Log Splitter (2009)
General Assembly


Page 2 of 6



24AD597D766 LS33 Log Splitter (2009)
Quick Reference

Page 4 of 6








FIGURE 1