



Service Advisory w-115

Models: 139-786-190, 130-706F190, 130-736G190, 130-826H190,
131-706F190, 131-736G190, 131-826H190, 132-716F190,
132-736G190, 132-836H190, 133K696F190

Date: September 17, 1998

Subject: TRANSMISSION PARTS

The transmission service parts listed below have been superseded by the supplier to improve reliability. We recommend you update your Dealer Business System with the superseded parts numbers and comments. This information should be readily available to anyone in your dealership quoting parts prices.

Original Part Number	Description	Superseded Part Number	Description
AF-44076	RH Housing	HG-62586P	RH Housing w/Bearing
AF-44077	LH Housing	HG-62587	LH Housing w/Bearing
AF-44078	Input Pinion Gear	HG-62636	Input Pinion and Housing Assembly, including Input Shaft
AF-44081	Input Bearing Housing		
AF-44270	Input Shaft		
AF-44393	LH Axle	HG-62701P	Differential Assy w/Axles
AF-44392	RH Axle		

Warranty Allowance: This is being released for informational purposes only.

Service Manager	Parts Manager	Service Tech.	Service Tech.	Service Tech.

Circulate and Initial