

## Service Advisory

W-138

## **CHORE PERFORMERS**

**Model Affected:** 

W-56MC (12A-56MC790)

Serial Number Range Affected:

2006 Model Year Units

Date:

5/12/2006

Subject:

754-04101 Belt Replacement

Required Action: This repair is to be considered a Fix-As-Fail only.

## **SYMPTOMS:**

Affected model may experience the belt coming off of the pulleys or loss of drive due to belt slippage after use.

## **CORRECTIVE ACTION:**

Replace the 754-04101 (3/8" x 31.68") belt with the 754-0637A (3/8" x 31.25") belt.

Warranty: Normal warranty terms apply. Indicate Service Advisory **W-138** and **754-04101** as the original failed part on the claim. Repair time allowance is 0.3 Hrs.

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.