

## Service Kit 753-05398

Date: 6/19/2006

Subject: Service Replacement for the 618-0379 Hydrostatic Transmis-

sion

Models N/A Affected:

Read through and understand these instructions completely before proceeding with repair.

**PURPOSE:** This service kit is the service replacement for the 618-0379 (918-0379) hydrostatic transmission that is no longer available.

**NOTE:** These materials are prepared for use by trained technicians who are experienced in the service and repair of equipment of the kind described in this publication, and are not intended for use by untrained or inexperienced individuals. Such individuals should seek the assistance of an authorized service technician or dealer.

NOTE: Save this Instruction Sheet. Refer to it when ordering replacement parts.

## **Service Kit Contents**

(See Figure 1)

| ITEM | PART      | QTY | DESCRIPTION                          |
|------|-----------|-----|--------------------------------------|
| NO.  | NUMBER    |     |                                      |
| 1    | 618-04329 | 1   | TRANSMISSION ASSEMBLY: HYDRO         |
| 2    | 618-04317 | 2   | HUB ASSEMBLY: WHEEL: DOUBLE D        |
| 3    | 736-0227  | 2   | WASHER: FLAT: .390" x 1.500" x .134" |
| 4    | 710-3119  | 2   | SCREW: HEX: 3/8"-16 x .750:GR5:LOCK  |
| 5    | 769-02128 | 1   | THIS INSTRUCTION SHEET               |




FIGURE 1