



Service Bulletin

Date: July 18, 2000

Model(s): 2001 500 ATV
(Manual Transmission)

Bulletin No: 01-01A

VIN: 861T307055 through 881T307218

Product Line: ATV

Subject: Reverse Shift Lever

Condition: It has been determined that the weldment on the reverse shift lever on affected models does not meet the standards of Arctic Cat.

Solution: Replace the existing reverse shift lever on all affected ATV's.

■ **NOTE:** If any customer has taken possession of an affected ATV, please make arrangements with the customer to have the necessary service work completed.

Parts: Reverse Shift Lever Update Kit (p/n 0437-010) will be sent directly to your dealership. **Do not order from Arctic Cat Service Parts Department.** Your dealership Parts Account will be billed for the parts and credited upon receipt of a Warranty Claim Form from your dealership.

Warranty: A labor allowance of 0.7 hr will be paid per affected ATV.

A Warranty Claim Form of up to 10 vehicle identification numbers (VIN) will be accepted.

Write 01-01A in the Failure Code section of the Warranty Claim Form.

