



Service Bulletin

Date: September 25, 2000

Affected Model(s): 2001 ZR 500 EFI

Bulletin No: 01-04

VIN: Not Applicable

Product Line: Snowmobile

Subject: Clutching Decal

Condition: It has been determined that the incorrect clutching decal was affixed to the affected snowmobile. The incorrect decal does not call for a gearing change for 5,000 feet and above.

Solution: Replace existing clutching decal with new Clutching Decal (p/n 4611-324). If an affected snowmobile has been delivered to a customer, please notify the customer concerning this necessary change.

■ **NOTE: It is not necessary to remove the existing decal. Affix the new decal over the existing decal.**

Parts: The appropriate number of new Clutching Decal(s) (p/n 4611-324) will be shipped directly to your dealership.

Your dealership Parts Account will be billed and then credited upon receipt of Warranty Claim Form(s) from your dealership.

Warranty: A labor allowance of 0.1 hr will be paid per affected snowmobile.

A Warranty Claim Form of up to 10 vehicle identification numbers (VIN) will be accepted.

Enter 01-04 in the Failure Code section of the Warranty Claim Form.

We apologize for any inconvenience this error may have caused you.

