



Service Bulletin

Date: October 7, 2003

Product Line: Snowmobile

Bulletin No: 2004-1-05

Subject: Muffler

Affected Models / VIN:

Model: 2003 4-Stroke Touring
Model No. S2003ACFERUSG
VIN: All

Model: 2003 Bearcat Wide Track
Model No. S2003BCFWTUSS
VIN: All

Model: 2003 4-Stroke Touring
Model No. S2003ACFEROSG (International)
VIN: All

Model: 2003 Bearcat Wide Track
Model No. S2003BCFWTOSS (International)
VIN: All

Model: 2003 4-Stroke Trail
Model No. S2003ACFLCUSG
VIN: All

ATTENTION

This Bulletin expires October 7, 2004. To ensure that the necessary service work is complete in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to October 7, 2004. All warranty claims directly related to this issue will not be honored after October 7, 2004.

Condition: It has been determined that the existing (production) muffler on the affected models may need to be replaced.

■ **NOTE:** If there is an excessive heat buildup in the muffler, the muffler baffles may not withstand the excessive heat buildup. This condition may cause the baffles to separate.

Solution: If the existing muffler fails as described above, install Muffler Update Kit (p/n 0637-266).

Parts: Order an appropriate number of Muffler Update Kit(s) (p/n 0637-266) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

■ **NOTE:** Muffler Update Kit (p/n 0637-266) will include an upgraded muffler and tie bands for securing the muffler covers.

Warranty: A labor allowance of 0.3 hr will be paid per affected snowmobile.
Cat Tracker Claim: Enter BS200405 in the complaint section.
Manual Claim: Enter 0405 in the Complaint section.

