



Service Bulletin

Date: August 30, 2004

Product Line: ATV

Bulletin No: 2005-2-03

Subject: Clutch Nut

Affected Models / VIN:

2005 TRV 500 (Automatic Transmission) Models within the VIN Range of 4UF05ATV85T207460 - 4UF05ATV55T208484 (excluding vehicles reworked at Arctic Cat and shipped after June 25, 2004). 821 ATV's within the above VIN Range are affected. The remaining ATV's within the VIN Range have been reworked prior to shipment.

■ **NOTE:** To identify a reworked ATV, each shipping crate is marked with three lime-green horizontal lines in three of the upper corners. Reworked ATV's do not need any service work. Do not submit a claim for these ATV's.

Condition: It has been determined that Clutch Nut (p/n 3423-501) does not meet Arctic Cat specifications and may come loose while the ATV is being operated. If this occurs, severe engine damage may occur.

Solution: Install Clutch Nut Update Kit (p/n 0437-041) according to the instructions included in the kit.

Parts: Order an appropriate number of Clutch Nut Update Kit(s) (p/n 0437-041) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon return of a Warranty Claim Request form and the existing clutch nut.

Warranty: A labor allowance of 2.0 hr will be paid per affected ATV.
Cat Tracker Claim: Enter BA200503 in the Complaint section.
Manual Claim: Enter 503A in the Complaint section.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected ATV. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on ATV's with warranty claims is important.

ATTENTION

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to August 30, 2005. All warranty claims directly related to this issue will not be honored after August 30, 2005.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



0804