



Service Bulletin

Date: January 10, 2006

Product Line: Snowmobile

Bulletin No: 2006-1-08

Subject: Driven Pulley Sheave Adjuster

Affected Models/VIN:

All 2005 T660 Turbo ST (EB) and 2004 T660 Turbo Models

■ **NOTE:** For identification purposes, it is necessary to refer to only the last six digits of the VIN.

Condition:

Arctic Cat has determined that original plastic Sheave Adjuster (p/n 0648-440) on the above models does not meet Arctic Cat specifications and should be replaced. The driven pulley sheave adjuster may come loose during the operation of the snowmobile. If the sheave adjuster loosens, the drive belt will tighten. This condition may cause the snowmobile to creep forward while idling. A tightened belt may also cause difficult starting.

Solution:

Install Sheave Adjuster Kit (p/n 0748-690) per instructions included in the kit.

■ **NOTE:** A new aluminum sheave adjuster included in the kit will replace the original plastic sheave adjuster.

Parts:

Order an appropriate number of Sheave Adjuster Kits (p/n 0748-690) through normal parts-ordering channels. Your dealership Parts Account will be billed and then credited upon receipt of a Warranty Claim Request form.

Warranty:

A labor allowance of 0.2 hr will be paid per affected snowmobile.
Claim: Enter BS200608 in the Complaint section.

■ **NOTE:** Please remember that when submitting a claim, make sure to always enter the current mileage of each affected vehicle. In order for Arctic Cat to accurately assess warranty claims, an accurate recording of mileage on vehicles with warranty claims is important.

ATTENTION

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to January 10, 2007. All warranty claims directly related to this issue will not be honored after January 10, 2007

