



# Service Bulletin

**Date:** October 8, 2002

**Product Line:** Snowmobile

**Bulletin No:** 2003-1-10

**Subject:** Bellcrank Arms

**Affected Models / VIN:**

Affected Models: All 2002 ZR 440 Sno Pro Models - See List of Models Below

2002 ZR 440 Sno Pro  
Model No. S2002ZRBPRUSG

2002 ZR 440 Sno Pro (International)  
Model No. S2002ZRBPROSG

**Condition:** It has been determined that existing Bellcrank Arms (p/n 0605-598) do not meet Arctic Cat standards and must to be replaced.

**⚠ WARNING**

Do not operate or permit anyone to operate the affected snowmobile until Bellcrank Arm Update Kit (p/n 0637-235) has been installed.

**Solution:** Install new Bellcrank Arm Update Kit (p/n 0637-235) per kit instructions.

■ **NOTE:** A letter will be sent to all registered owners of the affected snowmobiles advising them to contact an authorized Arctic Cat snowmobile dealer to have the necessary service work completed. Registered owners will also be advised to contact the new owners of any affected snowmobile which has been sold.

**Parts:** Order an appropriate number of Bellcrank Arm Kit (p/n 0637-235) through normal parts-ordering channels. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

■ **NOTE:** Back orders will be shipped as soon as parts are available.

**Warranty:** A labor allowance of 0.6 hr will be paid per affected snowmobile.

■ **NOTE:** Both racers and consumers are covered under this bulletin warranty.

Only one vehicle identification number (VIN) per claim can be entered. Do not submit a group claim.

CatTracker Claim: Enter BS200310 in the Complaint section.

Manual Claim: Enter 0310 in the Complaint section.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1002