



# Service Advisory

**Date:** April 7, 2003

**Product Line:** ATV

**Advisory No:** SAA310

**Subject:** Cold-Weather Starting

**Affected Models:**

All 375 and 400 ATV Models

---

During the last winter months, Arctic Cat has received inquiries concerning cold-weather starting of the 375 and 400 ATV models during cold weather. After testing this condition, Arctic Cat has determined that there are various recommendations that may improve cold-weather starting.

If you or your customer is experiencing hard starting with the 375 and 400 models in cold weather (40° F / 4.4° C) or below, apply the following recommendations.

- First, refer to **Starting A Cold Engine** in an appropriate ATV Operator's Manual.
- If the ATV is still difficult to start, install #90 Starter Jet (p/n 5507-092) and/or use Arctic Cat SAE 5W-30 engine oil.
- Installing 20 amp/hr Battery Kit (p/n 0436-183) may also aid in cold-weather starting.

Thank you for your patience and understanding in this matter.

Sincerely,

Product Service Department  
Arctic Cat Inc.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



0403