


# MODEL 770 WEEDER CULTIVATOR



## SEQUENTIAL PARTS LIST MODEL 770

PART NO.	DESCRIPTION	PART NO.	DESCRIPTION
010044	SCREW	950605	ROCKERARM KIT LH
011102	SCREW	950606	HOUSING KIT
030017	BOLT	953603	LEADWIRE
031003	BOLT	953002	OVERLOAD CUT-OUT
040016	WASHER	956901	PALNUT
041003	WASHER	953801	MOTOR
051102	NUT	955209	INSULATOR
061301	WIRE RING	201038	SCREW
070024	BEARING	955204	FILTER COVER
120601	TRIGGER HOUSING SET	956701	HALF SHAFT
123402	PIGTAIL	956702	CRANKSHAFT
201012	ASSIST HANDLE	957401	FRONT GASKET
201030	SWITCH	957402	GASKET RH
201040	WING NUT	957403	GASKET LH
953601	WIRE CONNECTOR	959501	TECH LABEL
201044	SCREW	970307	BLADE BOLT
201110	ASSIST HANDLE SUPPORT	975211	FAN
201127	HARNESS ASSY.	975227	FLOATING BUSHING
201211	STRAIN RELIEF	975401	FOAM FILTER
235701	'O' RING	976507	GEAR
236501	ROCKERARM LH	976705	TUBE SLEEVE
236502	ROCKERARM RH	976802	TUBE
236706	BLADE PLATE	976903	BLADE
950201	CRANKSHAFT ASSY.	977601	SHEAR PIN
950301	GEAR ASSY.	977605	GROOVED PIN
950602	GASKET SET	977703	FLANGED BUSHING
950604	ROCKERARM KIT RH		

USA—770—77PH

MODEL 770

**The Green Machine®**

[www.mymowerparts.com](http://www.mymowerparts.com)