

Homelite®

DEALER INFORMATION, TECHNICAL
ADVICE AND PRODUCT INFORMATION
CAN BE OBTAINED AT THIS NUMBER

TECHNICAL SERVICE

1 - 8 0 0 - 4 3 8 - 9 4 7 5

BULLETIN

NO. H98A-014

SUBJECT: NEW HL SERIES GENERATORS

AFFECTS: HL2500 UT03697C
HL4400 UT03698B
HLE4400UT03703C

John Deere Consumer Products has introduced three new **Homelite®** HL generators. These units use the same rotors and stators as the current **LR** series units.

Please note the **UT** number when ordering generator end parts; the rotors and stators of the units listed above **are not** interchangeable with other UT numbers of the same model. Listed below are the changes made.

HL 2500

UT-03697C

Bolt, Rotor: 48852-11

Rotor: A-02800-AS

Stator: A-02797-BS

HL 4400

UT03698B

HLE 4400

UT03703C

Bolt, Rotor: 48852-10

Bolt, Stator: 48853-07

Rotor: A-02799-AS

Stator: A-02796-BS



Peter Knoell
Product Service Manager

DATED: 11/98