





SERVICE 		7
		B0100002

English 1 (1)

SB, 340, 345, Oil pump, 2001-05

The material in the oil pump's cylinder has been changed from plastic to aluminium to ensure a longer lifetime and more effective lubrication.

Pump piston 5039321-01 remains unchanged.

Introduced from serial number:

H 340	011303151
H 345	011305251

New part no.	Description	Excl. part no.	Remarks
537 15 48-01	Pump cylinder	503 92 76-01	

