



SERVICE 		1 B0100007
--	--	-----------------------------

English 1 (1)

SB, 325 HS 75, 325 HS 99, Crankcase, 2001-01

When replacing crankcase 537 04 11-01 on hedge trimmers models 325 HS75 or 325 HS99 always use a crankcase with revision letter Y or later.

Crankcases with revision letters earlier than Y may only be used for trimmers, brushcutters or edgers.

