





SERVICE 		4
		B0100049

English 1 (1)

SB, 225, 227, 232, 240, Starting problems, 2001-10

It has been found that certain machines are difficult to start and/or have unreliable carburetor performance.

In the USA and Canada, these carburetors have part no. 537 05 27-01.

As well as checking the carburetor on machines that are difficult to start, the following measures should also be taken.

- 1 Make sure that the fuel filter sits in the bottom of the tank towards the front.
- 2 Screw in the idle adjustment screw so that it just touches the lever on the throttle shaft. Then screw in the screw a further 2.5 turns.
- 3 To ensure reliable start throttle operation, lubricate the choke shaft where it enters the hole in the carburettor housing. (See diagram). At the same time rotate the choke shaft back and forth a few times, until it moves freely.

IMPORTANT!

These models are fitted with fuel pumps and are normally very easy to start. It is extremely easy to flood (over-choke) the engine when the choke is used. Do not try to start more than 1–2 times with the choke out, then return the choke to the running position before trying to start again.

