



**Service
Bulletin**

**B0103009
2001-10**

Subject: "QUICK LIFT" HANDLE ROLL PIN - ALL ZT RIDING MOWERS

Effected Model Numbers:

All Serial Numbers prior to date code 0143, which is the first four digits of the serial number.

Service Information:

There have been isolated reports from the field that this roll pin, P/N 539101082, is breaking. If this should occur, the roll pin should be replaced with a solid steel groove pin.

Rotate the lift handle 90 degrees from its' normal position. Using a 5/32" pin punch, drive out the broken portion of the old roll pin. Rotate the lift handle back to the normal operating position.

Drive the new groove pin, small end first, into the handle, leaving 1/4" to 5/16" of the pin exposed. Be careful to align the pin with the groove guide in the handle.

Parts Information:

The part number on the new groove pin is:

539106532 - Groove Pin - 1 Required

Warranty Information:

Normal warranty procedures apply. Two (2) warranty time units will be allowed for this job.

