





| | | |
|---|--|----------|
| SERVICE  |  | 4 |
| | | B0200021 |

English 1 (1)

SB, 333, 335 XPT, 335 XPT California, Manifold, 2002-02

A new manifold has been introduced on the above models, integrating the manifold, retaining flange, and support sleeve into a single piece.

| | | |
|--------------------------------|-------------------|-----------|
| Introduced from serial number: | 335XPT | 020800001 |
| | 335XPT California | 020400001 |

| New part no. | Description | Excl. part no. | Remark |
|--------------|----------------|----------------|--------|
| 537 19 30-01 | Manifold assy. | 537 08 29-01 | |
| | Support sleeve | 503 78 99-01 | * |

* no longer in production, replaced by manifold assy. 537 19 30-01.

