





<b>SERVICE</b> 		<b>5</b>
		<b>B0200038</b>

English 1 (1)

## SB, 325 HD, 325 HS, Cooling air conductor, 2002-04

A new version of cooling air conductor has been introduced. The new version secures the HT lead in a better position and reduces the risk of the HT lead becoming trapped against the cylinder or flywheel.

New part no.	Description	Excl. part no.	Remark
537 17 23-01	Cooling air conductor	537 01 41-01	*

\* Still available as spare part for trimmers and brushcutters

