



SERVICE 		4
		B0200048

English 1 (2)

SB, 340, 345, 350, 346, 351, Carburettor, 2002-08

A mechanical catch has been introduced for the choke valve to ensure a better seal between the carburettor housing and choke valve and to improve starting abilities.

The paper pump gasket for the carburettor assembly has been replaced with a rubber gasket.

New and old parts are fully compatible.


HDA 196 (EPA) introduced from serial number:

340	022300801
350	022600001
345	022505301
346	022600001
351	022600001


HDA 195 introduced from serial number:

340	023102401
345	023100001
350	023106101

New ref. no.	Description	Excl. ref. no.	Remark
503 28 18-12	Carburettor HDA 195	503 28 18-03	340, 345, 350, 351
503 28 18-13	Carburettor HDA 196	503 28 16-14	EPA, 340, 345, 350, 346, 351
501 66 69-01	Pump gasket	503 80 06-01	
537 15 81-01	Spring	503 56 25-01	
537 15 82-01	Lever	504 86 04-08	
537 15 79-01	Choke shaft	503 94 53-01	
537 15 80-01	Lever		
501 46 85-01	Choke stop ball		
501 46 84-01	Choke stop spring		



N compl 503 28 18-12 Walbro HDA 195
compl 503 28 18-13 Walbro HDA 196 (EPA)



① 501 66 84-01
Set of gaskets
Dichtungssatz
Jeu de joints
Juego de juntas
Packningssats