





SERVICE 		8
		B0200060

English 1 (1)

SB, 325 HDA 55, 325 HE 3, 325 HE 4, 326 HDA 55, 326 HE 3, 326 HE 4, Gear housing, 2002-09

A limited batch of cutting heads has an additional shim between the cutting head and the gear housing. To make these cutting heads easier to identify there is a black dot on the gear housing. If it is necessary to replace gear housing 537 12 55-01 on a cutting head from this range of serial numbers the shim must **not** be refitted.

Note that the range of serial numbers given refers to the serial numbers on the cutting heads, not the machines.

New part no.	Description	Excl. part no.	Remark
531 00 49-91	Shim		
Introduced from serial number:			
	W261721 – W261760	HDA55	
	W293961 – W294800	HDA55	
	W301001 – W302642	HDA55	
	W285551 – W285590	HE3/HE4	
	W295801 – W297640	HE3/HE4	

