



SERVICE 		7
		B0200067

Replaces B0200042

English 1 (1)

SB, 315 Electric, 316 Electric, 318 Electric, Oil seals, 2002-09

Two new seals have been introduced to improve the seal around the oil filler hole and between the oil pump and oil tank.

Introduced from serial number:	315 Electric	21709196
	316 Electric	21809808
	318 Electric	21709433

New part no.	Description	Excl. part no.	Remark
508 04 35-07	Oil seal		
508 03 18-11	Oil tank	508 03 18-10	
508 04 35-06	Pump seal	508 04 35-02	
508 04 33-14	Pump assembly	508 04 33-13	
508 03 18-20	Field-fix		

