





SERVICE 		1 B0200069
--	--	-----------------------------

English 1 (1)

SB, 385 XP, Crankshaft, 2002-10

To extend its lifetime and reliability the crankshaft has been modified in a number of ways. Parts are fully interchangeable.

- specially developed needle bearing.
- revised hardening treatment for clutch thread.

New part no.	Description	Excl. part no.	Remark
503 99 34-73	Crankshaft assy.	503 99 34-72	

Introduced from serial number: 385 XP 023000001

