



SERVICE 		13
		B0200071

English 1 (1)

SB, 340, 345, 350, 346, 351, Clutch puller, 2002-10

The puller has been modified so that it is a better fit with clutch 537 11 05-01, see bulletin B0200020.

Puller 502 54 16-01 can be modified as explained in the description below.

New part no.	Description	Excl. part no.	Remark
502 54 16-02	Clutch puller	502 54 16-01	

