



<b>SERVICE</b> 		<b>6</b>
		<b>B0300005</b>

English 1 (1)

## SB, 371 K, Starter, 2003-01

A number of modifications have been made to the starter to increase its reliability and extend its working life. The pulley has been replaced by a kit that can also be fitted to earlier versions of starters.

- An O-ring has been fitted to the hub to prevent dust from penetrating and causing wear.
- A spring has been fitted to the hub to reduce vibration and wear between the starter housing and the pulley.

New part no.	Description	Excl. part no.	Remark
506 35 41-71	Starter assy.	503 62 81-72	
506 36 81-01	Pulley kit	506 26 95-01	
506 35 39-01	Sleeve		
506 25 30-01	Spring		
740 43 13-00	O-ring		
506 35 40-01	Washer		
503 21 06-19	Screw STC6SF 5.5 x 19		

Introduced from serial number: 371 K 024600119

\*compl 506 35 41-71

