





<b>SERVICE</b> 		<b>13</b>
		<b>B0300044</b>

English 1 (1)

## SB, 322, 323, 325,326, Bevel gear, 2003-07

A new bevel gear is now available for the above models. The new gear features a number of improvements over the previous version.

1. Stronger cogs. (Gear ratio is the same as before).
2. The gear housing has a larger diameter where it meets the driver. The diameter is reduced further up the housing to prevent grass that gets wrapped around the gear housing from jamming the cutting attachment.
3. Metal cup that prevents dirt from getting in underneath the driver.
4. The hole for the locking pin has been moved. The locking pin is now inserted in the gear housing parallel with the blade shaft.

The new bevel gear is compatible with older machines.

The earlier bevel gear, part no. 503 94 11-01, will be discontinued, as will the cog set and gear housing. These parts will be replaced with a new bevel gear assembly.

The new bevel gear will be brought into production around week 33.

New part no.	Description	Excl. part no.	Remark
537 19 92-02	Bevel gear	503 94 11-01	
	Gear housing	503 94 12-01	*
	Cog set	537 04 10-01	*

\* Replaced with 537 19 92-02

\*compl 537 19 92-02

