





SERVICE 		8
		B0300056

English 1 (1)

SB, 325 P 5, 326 P 5, 325 HE 4, 326 HE 4, Impact guard, 2003-09

An impact guard, part no. 537 17 45-01, is now available for the above products.

This part is also fitted to machines produced from week 0327.

The following points should be noted if the guard is fitted to earlier machines:

- 1 If a guard plate, part no. 537 03 41-01, is fitted to the machine, it must be removed before fitting the impact guard.
- 2 On machines manufactured before week 0327, the clamp sleeves, part no. 537 03 23-01 and vibration damping elements, part no. 537 03 24-01, must be replaced with a kit, part no. 537 30 96-01. The kit contains clamp sleeves and vibration damping elements. The clamp sleeves have movement limiters to prevent excessive flexing of the drive shaft.

See service bulletin B0300037.

NOTE! The screw, part no. 503 21 75-16, and washer, part no. 503 23 00-42, are not part of the impact guard, part no. 537 17 45-01.

New part no.	Description	Excl. part no.	Remark
537 17 45-01	Impact guard		
503 21 75-16	Screw		
503 23 00-42	Washer		

