



SERVICE 		13
		B0400013

English 1 (1)

SB, 357 XP, Crankcase puller, 2004-01

A service tool has been produced in order to split the crankcase and press out the crankshaft.

New part no.	Description	Excl. part no.	Remark
537 33 48-01	Puller		

