



SERVICE	B0403003
BULLETIN	2004-04

Subject: Fuel caps on commercial walk behind and zero turn mowers

Models Affected: Part number 539107598

Service Information: Due to possible manufacturing inconsistencies, we have seen instances where the new gray fuel cap might tighten during operation and be hard to remove. In instances where this occurs, use replacement gas cap, part number 539106188. Fuel caps should be replaced on new units prior to sale to eliminate the possibility of this situation. Pictured below are the old and new gas caps.

Warranty information: Normal warranty applies. No labor allowance will be offered



OLD GAS CAP pn 539107598



NEW GAS CAP pn 539106188