

MODEL 244 RX, 36 R

CRANKCASE, IGNITION SIDE

When mounting SEM AM7 coil instead of a SEM AM5 coil, the following adjustment has to be made.

The hole distance is 37 (+0.5) mm for AM7 compared to 46.5 (+0.5) mm for AM5.

Sleeve 502 05 65-02 is excluded.





CARBURETTOR WALBRO WT 17 B BECOMES WT 17 C

In order to achieve better durability and longer lifetime, the carburettor is improved on the following points:

502 10 03-03 Carburettor compl.	replaces	502	10	03-02
502 11 94-01 Choke shaft compl.	replaces	502	10	23-01
502 11 95-01 Screw with lockwasher	replaces	501	46	88-01
502 11 96-01 Throttle return spring	replaces	502	10	24-01
502 11 97-01 Choke return spring	replaces	506	02	82-01
502 11 98-01 Choke shaft circlip	replaces	505	31	67-36
502 12 01-01 Choke shaft compl. with circlip	new part			

SAW BLADE – MULTI 255

The saw blade Multi 255, 501 91 05-01 has been replaced by 501 91 05-02.

10: X 85. 106-96 8. 4 8-85

www.mymowerparts.com