



MODEL }
MODÈLE } **L 65**

FLYWHEEL BOSCH

Our subsupplier has stopped the delivery of flywheel 501 43 06-02 (Bosch).

For future spare parts needs, a new ignition system must be used.

1 pc flywheel SEM	501 83 20-01
1 pc stator plate	501 83 19-01
1 pc screw	501 69 58-01

The change will be introduced May -88.

VOLANT BOSCH

Notre sous-traitant a cessé la production du volant Bosch 5014306-02.

Au besoin il faut monter un autre allumage comprenant les pièces suivantes:

1 volant SEM	5018320-01
1 stator SEM	5018319-01
1 vis de fixation	5016958-01

Introduction à partir de 88-05.

Please turn over
Tournez s.v.p.

