



SERVICE 		8
		X 89.118-26

MODELS 40,45

THROTTLE CATCH

In order to improve the throttle cable housing attachment in the rear handle, a stop cleat is introduced on the throttle trigger lockout.

New Ref. No.	Description	Excluded Ref. No
506 01 45-04	Throttle trigger lockout	506 01 45-02
The change is introduced on the model:		
	40 from serial number	9050401
	45 from serial number	9050297

