



MODEL 40/45

WEAR PROTECTION FOR OIL TANK

The model 40/45 is a saw which of course is used in the woods but also is very popular at building sites when cutting timber. When the saw is not in use, it is often placed on a concrete floor, where it is left to idle. Vibrations of the engine inevitable leads to wear of the lowest located part of the oil tank bottom. The wear results in oil leakage and a replacement of crankcase/tank will be necessary.

In order to remedy this "problem", we have increased the thickness of the material in the bottom of the tank. This measure has increased the life, but sooner or later a leakage will occur.

We have therefore introduced a wear protection which is integrated with the chain catcher. The chain catcher/wear protection is only available as a spare part and should be sold to customers who use the saw at building sites. We do not recommend this part at forestry work.

Forestry work = Chain catcher 506 03 16-04
 Building sites = Chain catcher/wear protection 503 52 74-01

