





SERVICE 		<b>5</b>
		X 91.121-26

## MODEL 165 RX

### SILENCER SA

To make it easier to clean the spark arrestor fitted to the silencer, a new silencer has been introduced which allows access to the mesh from above.

**NOTE!** The spark arrestor mesh must be cleaned regularly, at least once a week. If the mesh is damaged it must be replaced.

If the mesh is blocked the saw will overheat and the cylinder and piston maybe damaged.

Also see the chapter on the silencer in the operator's manual.

The new silencer is introduced into production from serial no. 1090001.

New Ref. no.	Description	Excluded Ref. no.	Remarks
502 15 49-03	Silencer SA	502 15 49-02 502 17 77-01	
502 26 39-01	Spark arrestor mesh	502 11 25-01	*
502 26 40-01	Cover		
503 21 27-10	Screw		

\* Remains available as spare part.

