



SERVICE 		10
		X 91.141-26

MODEL 165 RX

BEVEL GEAR

A new bevel gear with strengthened bearing housings and more reliable locking of the bevel gears has been introduced.

Damaged or worn gears should not be repaired (because of worn bearing housings). We recommend that the complete bevel gear is always replaced (also applies to earlier bevel gears ref. no. 502 10 70-01).

The new bevel gear is therefore only available as a complete unit, ref. no. 502 10 70-03. Manufacture of the new bevel gear began from date code 91-08.

Introduced into production from serial no. 1090001.

New Ref. no.	Description	Excluded Ref. no.	Remarks
502 10 70-03	Bevel gear complete	502 10 70-01	
	Gear housing	502 10 71-01	
	Gear wheels set	502 10 82-01	
	Gear housing cover complete	502 10 69-01	
	Ball bearing	738 22 02-15	*)
	Spacer ring	502 12 24-01	*)
	O-ring	740 42 24-00	*)
	Spring	502 01 40-01	

*) Remain available as spare parts (used in other products).

NOTE! When changing sealing ref. no. 740 51 13-01 or O-ring ref. no. 740 48 25-01 the stop nut ref. no. 502 10 77-01 should be fixed with Loctite when fitted.

* compl. 502 10 70-03

