





SERVICE 		1
		X 95.004-26

23 LC

Connecting rod

In the spare parts list for 23/26LC/L/R 1.1993 no 106 23 37-63 the wrong ref. no. for the connecting rod is stated.

The connecting rod in box J has the ref. no. 530 01 09-60. This number only applies to 26 LC/L/R.

The connecting rod for 23 LC should have the ref. no. 530 01 40-05.

J *compl 530 01 40-16

