



Model 240RBD

Flexible shaft coating

We have decided to remove the rotating stop on the flexible shaft coating to improve manoeuvrability and at the same time increase the service life of the coating. This has been done at the end of the coating located by the throttle. Tilting of the cutting tool has been significantly improved by this measure.

However, you must be attentive to the cabling holding the throttle cable and the short-circuiting cables so that these do not wrap around the flexible coating.

The throttle cable can be stretched and cause unintentional acceleration.

This modification will be introduced into production during week 33; i.e. from serial number 633.

On older machines it's easy to file off the stop in the coating's groove, see fig. below.

