



For Husqvarna Parts Call 606-678-9623 or 606-561-4983



<b>SERVICE</b> 		<b>8</b> <b>B9900009</b>
--	--	-----------------------------

English 1 (3)

## **SB, 39, 240, 245, 250, 252, Overview table, 1999-03**




Update to overview table for throttle cables.

Replaces earlier version of service bulletin 97-10-10 flap 8.

## Throttle cables

Model	Ref.no.	L1 liner etc.	L2 cable projection etc.	Serial no.	Nipples	Remarks
250R	- 1993	502 27 29-01	1000 ±5	120 ±1		Forefinger-operated throttle control 502 28 06-01. Throttle cable enters underneath the engine. Steel liner.
250R	1994 -	502 27 29-06	965 ±5	162 ±1		Forefinger-operated throttle control 502 28 06-01. Steel liner for cable is replaced with 502 27 93-03.
250R	- 1996	502 27 93-03	965 ±2	152 ±1	>6520029	Forefinger-operated throttle control 502 28 06-01. Brown Teflon liner.
250R	1997 -	502 27 93-04	640 ±2	115 ±1	>7180059	Forefinger-operated throttle control 502 28 06-01. Brown Teflon liner. The cable is routed through the crankcase. Replaced with 537 03 71-02 and 537 02 42-02.
250R	1998 -	537 03 71-02	640 ±2	115 ±1	>8500001	Forefinger-operated throttle control 502 28 06-01. Black plastic liner. Cable diameter 0.9. Kit including air filter holder and rubber gaiter.
250R	1998 -	537 02 42-02	640 ±2	115 ±1	>8500001	Forefinger-operated throttle control 502 28 06-01. Black plastic liner. Cable diameter 0.9.
250RX	1995 -	502 27 29-07	795 ±5	133 ±1		Thumb-operated throttle control 502 28 37-01. Steel liner replaced with 502 28 60-03.
250RX	1996 -	502 28 60-03	810 ±2	116 ±1	>6450153	Thumb-operated throttle control 502 28 37-01. Brown Teflon liner.
250RX	- 1997	502 28 60-06	810 ±2	116 ±1		Thumb-operated throttle control 502 28 37-01. Brown Teflon liner. Cable diameter 0.9.
250RX 252RX	1997 - 1997 -	502 28 60-04	840 ±2	80 ±1	>7170157	Thumb-operated throttle control 502 28 37-01. Brown Teflon liner. The cable is routed through the crankcase. Replaced with 502 28 60-05.
250RX 252RX	1997 - 1997 -	502 28 60-05	840 ±2	80 ±1	>7420190 >7430001	Thumb-operated throttle control 502 28 37-01. Brown Teflon liner. The cable is routed through the crankcase. Cable diameter 0.9. Replaced with 537 03 71 and 537 02 42-01.

## Throttle cables

Model	Ref.no.	L1 liner etc.	L2 cable projection etc.	Serial no.	Nipples	Remarks		
252RX	1998 -	537 03 71-01	840±2	80 ±1	>8450073		Thumb-operated throttle control 502 28 37-01. Black plastic liner. Cable diameter 0.9. Kit including air filter holder and rubber gaiter.	
252RX	1998 -	537 02 42-01	840 ±2	80 ±1	>8450073		Thumb-operated throttle control 502 28 37-01. Black plastic liner. Cable diameter 0.9.	
39R	- 1998	502 11 82-01	916 ±1	67 ±5			Forefinger-operated throttle control 502 12 18-03.	
240/245R	- 1994	502 11 82-01	916 ±1	67 ±5			Forefinger-operated throttle control with lock 502 12 18-03.	
240/245R	1994 -	502 27 93-01	895 ±2	95 ±1			>4110001	Forefinger-operated throttle control 502 28 06-01.
245RX	- 1994	502 11 82-02	792 ±1	67 ±5				Forefinger-operated throttle control 502 12 18-03.
245RX	1994 -	502 27 93-02	795 ±2	97 ±1	>411001		Forefinger-operated throttle control 502 28 06-01.	
245RX	1995 -	502 28 60-01	700 ±2	61 ±1	>5510267		Thumb-operated throttle control 502 28 37-01. Brown liner. Replaced with 502 28 60-08.	
245RX	1997 -	502 28 60-08	700 ±2	61 ±1			Thumb-operated throttle control 502 28 37-01. Brown plastic liner. Cable diameter 0.9.	