



Service
Note

N0101001

2001-02

Page 1 (1)

Models

Affected: 225 HBV / 225 HBV Lite

Subject: Spacer Orientation During Reassembly

Action Required:

The subject blowers use a spacer (part # 531 03 03-77) that is machined on one side and flat on the other. This causes some confusion when reassembling the unit after repairs are made.

Please review the attached diagram showing how the spacer should be oriented during reassembly. The spacer should be installed with the flat side toward the engine assembly and the machined side toward the fan.

