




Product Service Bulletin



100998-11

1998-11

Engineering Services

Models Affected:

136, 141

Serial Numbers: Beginning 98100Nxxxx through 98265Nxxxx.

NOTE: This serial number is located on the EPA label attached to the engine cover just above the starter cover. Do not use the serial number on the metal tag by the clutch cover for this bulletin.

Issue Reported: Units in the serial range listed could possibly have been shipped with a poor or improperly fitted oil cap. The cap may also be difficult to install or remove.

Action Required: Remove and tag the affected oil cap for warranty return. Order replacement oil cap, part # 501 76 56 02 and install in unit.